

THE CARLYLE BUILDING

CHICAGO, IL



Before



After

Project: North and South Sundek Restoration

Owner Reference: The Carlyle Apartments Homeowners Assn

Engineer Reference: CTL Group

ICRI AWARD: *Award of Excellence for Special Projects*

Scope:

- Remove Existing Roof & Railing Systems
- Cast New Structural Concrete Curb
- Install New Hydro Tech Roofing System
- Concealed Tie-Back System
- Hanover Paver System
- Sterling Dula Railing System
- High Performance Coatings

Site Conditions:

- 39 Story Residential Condominium